

Dixon Sand Quarry Hearses Rd and intersection of Wisemans Ferry Rd
Maroota NSW 2756

TEOM PM10 Monitoring Data
EPL 12513 Point 1

Sampling Frequency Monthly summary
Date Sampled Continuous (15min)

Results Obtained 18/09/2015
Results Published 2/10/2015

Point 1 Aug-15	24 Hour PM ₁₀ (ug/m ³)	Annual PM ₁₀ Average (ug/m ³)	Annual PM ₁₀ Average Criteria	24 hour PM ₁₀ NEPM Criteria	24 hour PM ₁₀ EPL Trigger Value	Requirement Met	Notes
1/08/2015	8.0	8.2	30	50	42	Yes	
2/08/2015	10.3	8.2	30	50	42	Yes	
3/08/2015	6.9	8.2	30	50	42	Yes	
4/08/2015	7.2	8.2	30	50	42	Yes	
5/08/2015	6.7	8.1	30	50	42	Yes	
6/08/2015	9.5	8.2	30	50	42	Yes	
7/08/2015	8.4	8.2	30	50	42	Yes	
8/08/2015	13.2	8.3	30	50	42	Yes	
9/08/2015	15.8	8.5	30	50	42	Yes	
10/08/2015	7.5	8.5	30	50	42	Yes	
11/08/2015	9.2	8.5	30	50	42	Yes	
12/08/2015	10.9	8.5	30	50	42	Yes	
13/08/2015	6.9	8.5	30	50	42	Yes	
14/08/2015	9.7	8.5	30	50	42	Yes	
15/08/2015	14.9	8.7	30	50	42	Yes	
16/08/2015	23.5	9.0	30	50	42	Yes	
17/08/2015	6.1	8.9	30	50	42	Yes	
18/08/2015	10.4	9.0	30	50	42	Yes	
19/08/2015	26.9	9.3	30	50	42	Yes	
20/08/2015	21.4	9.6	30	50	42	Yes	
21/08/2015	15.9	9.7	30	50	42	Yes	
22/08/2015	15.7	9.8	30	50	42	Yes	
23/08/2015	9.2	9.8	30	50	42	Yes	
24/08/2015	7.3	9.7	30	50	42	Yes	
25/08/2015	4.2	9.6	30	50	42	Yes	
26/08/2015	6.1	9.6	30	50	42	Yes	
27/08/2015	3.1	9.5	30	50	42	Yes	
28/08/2015	6.1	9.4	30	50	42	Yes	
29/08/2015	5.3	9.3	30	50	42	Yes	
30/08/2015	9.2	9.3	30	50	42	Yes	
31/08/2015	9.2	9.3	30	50	42	Yes	

Dixon Sand Quarry Hearses Rd and intersection of Wisemans Ferry Rd
Maroota NSW 2756

Static Deposition Dust
EPL 12513

Sampling Frequency: Monthly
Sample Date: 24/08/2015
Sample Time: 10:57 AM
Sampled By: TW (VGT)

Results Obtained 31/08/2015
Results Published 14/09/2015

Aug-15	Deposited Dust mg/m ² /mth	Annual Average (Jul15-Jun16) mg/m ²	Annual Average Limit mg/m ²	Requirement Met	Notes
Point 3	8.9	5.5	4.0	No	Dixon Quarry did not operate for the majority of the monitoring period. The high result could have been attributed to agricultural burn offs, grass slashing by the resident and/or clean up in the vicinity of the static dust gauge.